BACK TO MAIN TOC

Appendix C: Results from Rebound Tests (Schmidt Hammer Tests)




Figure C1: Column C1 – Fabric Formwork, Normal Concrete.




Figure C2: Column C2 – Cardboard Tube, Normal Concrete.




Figure C3: Column C3 – Fabric Formwork, Flyash Concrete.




Figure C4: Column C4 – Cardboard Tube, Flyash Concrete.




Figure C5: Column C5 – Fabric Formwork, Normal Concrete.




Figure C6: Column C6 – Cardboard Tube, Normal Concrete.

See Also

Place text here.

From:
https://fabwiki.fabric-formedconcrete.com/ - **FabWiki**

Permanent link:
https://fabwiki.fabric-formedconcrete.com/doku.php?id=fabwiki:research:canada:delijani:appendix_c

Last update: **2023/10/15 20:28**