

# Chapter 2 Discussion

It appears that the sides of the box made for testing using normal concrete, Figure 8, were not covered with duct tape or made of a material that would have prevented water from being absorbed into it. I wonder what impact that might have had on the results. Conversely the box used for Test 2, Figure 14, appears to be coated in a non-absorptive material. [RPS]

From:

<http://fabwiki.fabric-formedconcrete.com/> - **FabWiki**

Permanent link:

[http://fabwiki.fabric-formedconcrete.com/doku.php?id=talk:fabwiki:research:canada:delijani:chapter\\_2](http://fabwiki.fabric-formedconcrete.com/doku.php?id=talk:fabwiki:research:canada:delijani:chapter_2)

Last update: **2023/11/03 16:21**

